
F | G. 1









FIG.3A




F1G.3




Lerner-Method of Warning Individuals About Staves
(NCLUDING COCKTOPS 4/8




Gerner-Method of Warning Industrals About the Tourfaces on Stoves Including Cooktops 5/8



Lerner-Memod of Warning Individuals ABOUT HOT SURFACES ON STOVES INCLUDING COOKTOPS



Lerner- Method of Warning Findwaldval ABOUT HOT Surfaces, on Stoves Ficluding Cooktops 7/8



Lerner-Method of Warning Individuals ABOUT HOT Surfaces on Stoves Including Cocktops 8/8

